

# **ASBESTOS CONTAINING MATERIAL NOTIFICATION**

## ***STUDENTS, EMPLOYEES, AND BUILDING OCCUPANTS***

**Asbestos Containing Materials (ACM) may be present in some University of Florida buildings. Typical asbestos containing materials that may be present in this building include pipe insulation, spray applied ceilings, fireproofing, asbestos cement panels (fume hood linings, lab table tops), plaster, and floor tile. Buildings constructed after 1981 are less likely to contain asbestos products though surveys are required prior to any renovation activity regardless of the age of the building.**

**Asbestos in an undisturbed state poses no significant health concerns. Before disturbing or removing any building material verify its content by contacting a UF asbestos representative. Any damage to ACM should be reported to Environmental Health and Safety.**

**Contact Information:  
University of Florida  
Environmental Health and Safety  
(352) 392-3393**